

EFFECTIVENESS OF TYRE CHIPS AS
ALTERNATIVE MATERIAL IN GABION
WALL TO ENSURE SLOPE STABILITY

MOHAMMAD AMIRUL SYUKRI BIN MD
ZIN

B. ENG(HONS.) CIVIL ENGINEERING

UNIVERSITI MALAYSIA PAHANG



SUPERVISOR'S DECLARATION

I/We* hereby declare that I/We* have checked this thesis/project* and in my/our* opinion, this thesis/project* is adequate in terms of scope and quality for the award of the Bachelor Degree of Civil Engineering

(Supervisor's Signature)

Full Name : DR. AMIZATULHANI BINTI ABDULLAH

Position :

Date :



STUDENT'S DECLARATION

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at Universiti Malaysia Pahang or any other institutions.

(Student's Signature)

Full Name : MOHAMMAD AMIRUL SYUKRI BIN MD ZIN

ID Number : AA14113

Date : 12 JUNE 2018

EFFECTIVENESS OF TYRE CHIPS AS ALTERNATIVE MATERIAL IN
GABION WALL TO ENSURE SLOPE STABILITY

MOHAMMAD AMIRUL SYUKRI BIN MD ZIN

Thesis submitted in fulfillment of the requirements
for the award of the
Bachelor Degree in Civil Engineering

Faculty of Civil Engineering and Earth Resources
UNIVERSITI MALAYSIA PAHANG

JUNE 2018

ACKNOWLEDGEMENTS

The completion of this thesis could not have been possible without the participation and assistance of so many people whose name may not all be enumerated. Their contributions are sincerely appreciated and gratefully acknowledge. I would like to express my deep appreciation and indebtedness particularly to the following:

Dr Amizatulhani Binti Abdullah, my supervisor for this final year project, for her guidance and endless support, kind and understanding spirit during this case research.

To all my colleagues, friends and especially my family who in one way or another shared their support, either morally, financially and physically, thank you.

Above all, to the Great Almighty, the author of knowledge and wisdom, for His countless love and for giving me strength and ability to understand, learn and complete this thesis.

Thank you.

ABSTRAK

Kegagalan cerun adalah bahaya geoteknikal yang serius di banyak negara di dunia termasuk Malaysia. Kegagalan cerun adalah satu fenomena dimana cerun runtuh secara tiba-tiba akibat lemahnya daya tahan diri bumi di bawah pengaruh hujan atau gempa bumi. Untuk projek ini, kestabilan cerun akan dikaji untuk mencegah kegagalan cerun berlaku. Langkah pencegahan perlu diambil untuk mengelakkan kemerosotan tanah daripada runtuh atau gagal. Untuk kajian ini, jenis dinding penahan gabion akan digunakan. Dinding gabion adalah tembok penahan yang terbuat dari batu yang disusun dan diikat bersama dengan dawai. Dinding Gabion biasanya bersudut ke arah cerun, atau disusun secara bertangga, dan bukan disusun secara menegak. Batu atau kerikil diklasifikasikan sebagai sumber yang tidak boleh diperbaharui yang akan terhad pada suatu masa akan datang pada masa akan datang. Untuk kajian ini, bukannya hanya batu, tetapi campuran batu dan serpihan tayar akan digunakan untuk mengisi dinding gabion. Model eksperimen dibangunkan untuk mensimulasikan tingkah laku cerun di bawah pengaruh hujan dengan sudut kritikal 60° . Berdasarkan analisis, dapat disimpulkan bahawa serpihan tayar adalah efektif sebagai bahan alternatif untuk dinding gabion bagi memastikan kestabilan cerun di bawah skala kecil.

ABSTRACT

Slope failure is a serious geotechnical hazard in many countries in the world including Malaysia. Slope failure is a phenomenon that a slope collapses abruptly due to weakened self-retainability of the earth under the influence of a rainfall or an earthquake. For this project, slope stability will be studied to prevent slope failure from happened. Preventive measure should be taken in order to prevent slope from collapse or fail. For this study, gabion types of retaining wall will be used. A gabion wall is a retaining wall made of stacked stone-filled gabions tied together with wire. Gabion walls are usually angled back towards the slope, or stepped back with the slope, rather than stacked vertically. Stones or gravel is classified as non-renewable resources which will be limited someday in the future. For this study, instead of gravel only, a mixture of tyre chips and stones will be use to fill the gabion wall. An experimental model is developed to simulate the behaviour of the slope under the influence of rainfall with a critical angle of 60° . Based on result analysis, it can be concluded that tyre chips is effective as alternate material for gabion wall to ensure slope stability under small scale.

TABLE OF CONTENT

DECLARATION

TITLE PAGE

ACKNOWLEDGEMENTS **1**

ABSTRAK **2**

ABSTRACT **3**

TABLE OF CONTENT **4**

LIST OF TABLES **7**

LIST OF FIGURES **8**

CHAPTER 1 INTRODUCTION **9**

1.1 Background of Study 9

1.2 Problem Statement 9

1.3 Objectives of Study 10

1.4 Scope of Study 11

CHAPTER 2 LITERATURE REVIEW **12**

2.1 Malaysia's Climate / Weather 12

2.2 Introduction to Slope Failure 14

2.3 Mode of Slope Failure 15

2.3.1 Plane failure 16

2.3.2 Wedge Failure 16

2.3.3 Toppling failure 17

2.3.4 Rockfalls 19

2.3.5 Rotational Failure 19

2.4	Cases of Slope Failure in Malaysia	20
2.5	Current Practice / Method to Ensure Stability of Slope	23
2.5.1	Drainage and water control	23
2.5.2	Soil nailing	25
2.5.3	Geosynthetics reinforcement	28
2.5.4	Retaining wall	29
2.6	Waste Tyres	34
2.7	Tyres Recycling Activities	35
CHAPTER 3 METHODOLOGY		37
3.1	Introduction	37
3.2	Laboratory Test (Sand, Gravel, Tyres)	38
3.2.1	Sieve Analysis	39
3.2.2	Particle Density Test (Pycnometer)	39
3.2.3	Specific Gravity Test (Gravel and Tyre Chips)	40
3.2.4	Standard Proctor Test	41
3.2.5	Constant Head Permeability Test	42
3.3	Preparation of Material	43
3.4	Development of Slope Model	45
CHAPTER 4 RESULTS AND DISCUSSION		47
4.1	Introduction	47
4.2	Laboratory Test Results	48
4.2.1	Sieve Analysis	48
4.2.2	Particle Density Test and Specific Gravity Test	50
4.2.3	Standard Proctor Test	52

4.2.4	Constant Head Permeability Test	57
4.3	Slope Model's Result	60
CHAPTER 5 CONCLUSION AND RECOMMENDATION		65
5.1	Conclusion	65
5.2	Recommendation	66
REFERENCES		67

LIST OF TABLES

Table 4.1	Calculation for sieve analysis	48
Table 4.2	Specific gravity for sand	51
Table 4.3	Specific gravity	52
Table 4.4	Calculation for dry unit weight and water content for sand	53
Table 4.5	Calculation for dry unit weight and water content for gravel	54
Table 4.6	Calculation for dry unit weight and water content for tyre chips	55
Table 4.7	Calculation for dry unit weight and water content for mixture of tyre chips and gravel	56
Table 4.8	Coefficient of permeability for sand	58
Table 4.9	Coefficient of permeability of gravel	58
Table 4.10	Coefficient of permeability of tyre chips	59
Table 4.11	Coefficient of permeability of mixture of gravel and tyre chips	59

LIST OF FIGURES

Figure 2.1	Direction of wind in Monsoon season (Hassan, S.F, 2015)	13
Figure 2.2	Malaysia Annual Average Rainfall Graph (mm)	14
Figure 2.3	Common type of slope failure	16
Figure 2.4	Reported landslides and fatalities (1973-2007)	21
Figure 2.5	Highland tower collapse.	22
Figure 2.6	Sub-surface drainage.	25
Figure 2.7	Soil nail with centralizers.	26
Figure 2.8	Application of soil nail for reinforcing the slope.	27
Figure 2.9	Application of soil nailing in the field.	27
Figure 2.10	Gravity walls with different type of material.	30
Figure 2.11	Cross section view of a Cantilever wall.	31
Figure 2.12	Sheet piling wall in the soil.	32
Figure 2.13	Application of gabion wall at cut slope.	33
Figure 3.1	Methodology flow chart	38
Figure 3.2	Compaction curve	42
Figure 3.3	Cross section of the Perspex frame	44
Figure 3.4	Front view of the gabion wall and the Perspex frame	44
Figure 3.5	Arrangement of gabion wall at slope model	46
Figure 4.1	Particle size distribution curve for sand	49
Figure 4.2	Particle size distribution curve for gravel	49
Figure 4.3	Particle size distribution curve for tyre chips	50
Figure 4.4	Compaction curve for sand	53
Figure 4.5	Compaction curve for gravel	54
Figure 4.6	Compaction curve for tyre chips	55
Figure 4.7	Compaction curve for mixture of tyre chips and gravel	56
Figure 4.8	Movement of slope without gabion wall	60
Figure 4.9	Displacement of gabion with gravel material	61
Figure 4.10	Displacement of gabion with tyre chips material	62
Figure 4.11	Displacement of gabion with mixture of gravel and tyre chips material of (50 – 50)%	63
Figure 4.12	Gabion wall settled after exposed to the rainfall	64

CHAPTER 1

INTRODUCTION

1.1 Background of Study

Slope failure is a serious geotechnical hazard in many countries in the world including Malaysia. Slope failure is a phenomenon that a slope collapses abruptly due to weakened self-retainability of the earth under the influence of a rainfall or an earthquake. Slope failure, also referred to as mass wasting, is the downslope movement of rock debris and soil in response to gravitational stresses. Material is constantly moving downslope in response to gravity. Movement can be very, very slow, barely perceptible over many years or movement can be devastatingly rapid, apparent within minutes. Whether or not slope movement occurs depends on slope steepness and slope stability. For this project, slope stability will be studied to prevent slope failure from happening. Slope stability is the potential of soil covered slopes to withstand and undergo movement. Slope stability is based on the interplay between two types of forces, driving forces and resisting forces. Driving forces promote downslope movement of material, whereas resisting forces deter movement. So, when driving forces overcome resisting forces, the slope is unstable and results in slope failure. Preventive measure should be taken in order to prevent slope from collapse or fail. For this study, gabion types of retaining wall will be used. Gabion by definition is a cage filled with rocks, concrete, or sometimes sand and soil. A gabion wall is a retaining wall made of stacked stone-filled gabions tied together with wire. Gabion walls are usually angled back towards the slope, or stepped back with the slope, rather than stacked vertically. For this study, instead of stones only, a mixture of tyre chips and stones will be use to fill the gabion wall.

1.2 Problem Statement

In Malaysia, slope failure tragedy had happened so many times before and had caused so many death tragedies, injuries and property damages. As example, the biggest slope failure tragedy happened in 11 December 1993 at Taman Hillview, Ulu Klang,

Selangor. The slope failed after prolong rainfall for about 2 weeks and had destroyed 3 blocks of apartment and 48 fatalities. Slope failure also cause a major money spending for the cost of repairing the damages and reparation for the victims.

Nowadays, almost all people in the world own vehicles which used tyres to move. Life expectancy for tyres is almost 2 or 3 years and need to be changed to a new one afterwards. Up to this century, stockpiling of used tyres have been a problem to the environment. The used tyres cannot be bury as tyres are difficult to compact and do not decompose easily. Not only do tyres take up valuable landfill space, but over time they tend to float to the top, working their way up through the waste and soil. Once they break through the surface, the landfill's cover is broken, exposing its contents to insects, rodents, and birds and allowing landfill gases to escape. Besides that, if the tyre is burned or happened to catch a fire, the fires are extremely dangerous and the most difficult problem associated with stockpiled waste tires. These fires are difficult to extinguish as the materials that make tyres good fuel unfortunately also makes tyre fires difficult to put out. Large tyre fires can burn for a long time, depleting firefighting resources. It will also cause air pollution as the hazardous compounds and potentially toxic gases are released in the thick black smoke produced by tire fires. It will also contaminate the ground as the oil and ash created during fires can contaminate the ground, endangering the ground and surface waters, In order to reduce the stockpiling of used tyres, this study proposed the use the tyres as one of the materials in the gabion wall and the effectiveness are studied.

Stones or gravel is classified as non-renewable resources which will be limited someday in the future. As a preventive measure, this study will propose to reduce the use of stones/gravel in the gabion wall. The effectiveness of this method also are studied.

1.3 Objectives of Study

There are two (2) objectives for this study:

- To determine the basic properties of tyre chips and soil used in the study.

- To determine the effectiveness of tyre chips and gravel mixture as material in gabion wall to stabilize slope

1.4 Scope of Study

For this project, several types of laboratory tests were conducted to determine the basic properties of the soil. The types of laboratory test that were conducted include sieve analysis, particle density test for sand, specific gravity test for gravel and tyre chips, standard proctor test and constant head permeability test.

An experimental model was also developed to study the behaviour and movement of the slope under the influence of rainfall.

REFERENCES

Head, K. H., 1982, *Manual of soil laboratory testing*, Vol 2, Pentech Press, ISBN 0-7273-1305-3

ASTM International - Standards Worldwide. (2006). *ASTM C136-06*.

http://www.astm.org/cgi-bin/SoftCart.exe/DATABASE.CART/REDLINE_PAGES/C136.htm?E+mystore

Blake, G.R. 1965. *Particle density*. pp. 371-373. in *Methods of Soil Analysis, Part I*, Agronomy, No. 9, C.A. Black, ed., American Society of Agronomy, Madison, Wise

Proctors Test for Compaction of Soil – *Procedures, Tools and Results*. Retrieved from <https://theconstructor.org/geotechnical/compaction-test-soil-proctors-test/3152/>

Chew, Tien (2013). *The Monsoon Seasons in Malaysia*. Retrieved from <http://www.expatsgo.com/my/2013/06/28/the-monsoon-seasons-in-malaysia/>

R. P. Orense (2004). *Slope Failures Triggered by Heavy Rainfall*.

Ahmad, S. T. (2007). *Design Optimization Of Curve Profile Retaining Wall*.

Aminudin, A. R. (2009). *Analysis of slope failure at Maran highway using slope/w software*. Kuantan: faculty of civil engineering and earth resources.

Kazmi, D et.al. (2017). *Landslide of Highland Towers 1993: a case study of Malaysia. Innovative Infrastructure Solutions*. Springer International Publishing AG Switzerland.

Mahlangu, M. L. (2009). *Waste Tyre Management Problems In South Africa And The Possible Opportunities That Can Be Created Through The Recycling Thereof*.

Prashant, D. A. (2010). *Soil Nailing for Stabilization of Steep Slopes Near Railway Tracks*. Research Designs and Standards Organization (RDSO), Lucknow.

Shaw-Shong, L. (2005). *Soil Nailing for Slope Strengthening*. Gue & Partners Sdn. Bhd.

Zornberg, J. G. (2007). *New Concepts in Geosynthetic-Reinforced Soil*. Austin: The University of Texas.

Wyllie, Duncan C (2004). *Rock Slope Engineering: Fourth Edition*.

ANZECC (1994). Australia and New Zealand, Environment and Conservation Council. National Guideline for the Management of Waste Tyre: National Manifest and Classification System.

ASTMC (1994). Australian Scrap Tyre Management Council. Solving Australia's Scrap Tyre Disposal Problem: An Industry based Solution, mimeo.